

Firm credentials and case studies

4. Project Name: Delhi Golf Course, New Delhi

Location: New Delhi

Duration: July 2020- Present

Volume of water: 4.9 million liters

Nature of water: Extremely polluted water coming from the STP of the Delhi Golf Club.

Intervention

- Initially the sludge was removed from the pond and Aquaritin is dosed regularly.
- Water Quality is monitored on monthly basis.

S no	Parameter	Unit	Pre-treatment	Post-treatment	Percent Change
1.	BOD	mg/lit	178	6	-95.7%
2.	COD	mg/lit	512	22	-96.6%
3.	DO	mg/lit	0.7	7.1	+914.2
4.	TDS	mg/lit	704	540	-23.3%



Firm credentials and case studies

4. Project Name: Delhi Golf Course, New Delhi Location: New Delhi

- Water body condition before OXYFEED treatment.
- Pictures were taken on June 22, 2020.



Firm credentials and case studies

4. Project Name: Delhi Golf Course, New Delhi Location: New Delhi

- After first dosing of OXYFEED treatment.
- Development on June 24, 2020.

